

## Seoul Museum of Art Construction Works

Document number: ???- 02- A- 39

### Construction (Application) Record

#### 1. Company (supplier)

Name	ESAI Corp Ltd	Name of President	Young- hwan Lee	
Co. Type	Insuladd Wholesaler/Retailer	Co. Sub- type	Trading	
Address	250 Imjung- dong, Jung- ku, Seoul		Postcode	100- 853
Tel	02 2278 3337	Fax	02 2272 8046	
Co. Reg. No.	104- 81- 56846			

#### 2. Record of supply

Name of Project (Buyer)	Work carried out by	Work Period	Applied area (q'ty)	Purpose
Construction of Seoul Museum of Art	Hanil Construction Co Ltd	Aug 2001 – Nov 2001	Front lobby walls (720m2), Damp-proof walls in collection rooms (980m2)	Insulation and anti- condensation of major areas
Left blank hereafter				

This is to certify that the above is true and correct to the best of my knowledge.

26 January 2002

Sealed by: Lee, Dae- won

Chief Supervisor of

Seoul Museum of Art Construction Works



# Seoul Museum of Art

서울시립미술관이  
새 모습으로 당신을 맞이합니다.

